


2430 "E" Street, N. W.
Washington, D. C.
11 September 1953

25X1A9a



25X1A9a

Dear Mr. [REDACTED]:

25X1A9a


On Mr. [REDACTED] return from the [REDACTED] he reported generally that things were going well on the job, expressing some concern only with regard to the block masonry work on the Auxiliary Building. This matter is also mentioned in your progress report of 8 September 1953. This is a source of considerable concern to the undersigned, and it is hoped that the trouble will be corrected to the best of the Contractor's and your ability, especially in light of the fact that the block work is to be exposed. No doubt the four-inch units with the narrower joints will give a more satisfactory job. Paragraphs 11.15 and 11.19 of the Specifications appear most pertinent for use in insistence on satisfactory work in this category.

25X1A

25X1A9a

Mr. [REDACTED] also mentioned that the warehouse people expressed some concern about the condition of the road and the need to do something to make continued access to the building site possible, as the wet season gets underway. If you have not already done so, it may be well to discuss with the Contractor Paragraph 4 of the Specifications for the extra on the road in order to be assured that this provision will not result in the work not being done in time. Any revision you may agree to with the Contractor will be acceptable to the Contracting Officer.

Very truly yours,



25X1A9a